
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-189	Smoke	7/22/2009	ADS/TM	S15AA_045MH	Dry	Yes	782.61

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S15AA_054G1	S15AA_054DE	S15AA_039MH	153.747	8
S15CC_030G1	S15CC_030MH	S15AA_045MH	628.859	30

Observations & Photos

Obs_ID S1028-189-OB01

Address Lafayette Ave & Braddish Ave


Status Public

Source Catch Basin

Location Curb

Nearest MH S15AA_045MH

Comments Smoke from catch basin on the northwest corner of Lafayette Ave & Braddish Ave



Picture \S1028-189-OB01-P01.jpg

Comments Lafayette Ave & Braddish Ave looking west